


Sound Study 1 - November 2, 2015

Situation	No operations on site	Dock access road building & rock removal Excavating crew, 4 trucks & excavator	Unloading Federal Kivalina LH120 and trucks operating	Regular site operations Screener running, crusher running
Weather	<i>16 degrees celcius 10 Km/h wind and clear skies</i>	<i>20 degress celius less than 10 Km/h and cloudy skies</i>	<i>22 degrees celius less than 5 Km/h wind and clear skies</i>	<i>9 degrees celius less than 10 Km/h wind and clear skies</i>
Date:	<i>15 July 2015</i>	<i>22 July 2015</i>	<i>7Aug 2015</i>	<i>26 Oct 2015</i>
Time of day	<i>6:00 AM</i>	<i>10:00 AM</i>	<i>2:00 PM</i>	<i>3:00 PM</i>
1	<i>67.9</i>	<i>73</i>	<i>65.5</i>	<i>62.8</i>
2	<i>65.3</i>	<i>91*</i>	<i>64.4</i>	<i>66.9</i>
3	<i>65.5</i>	<i>82</i>	<i>65.6</i>	<i>66.7</i>
4	<i>67.5</i>	<i>76.3</i>	<i>59.6</i>	<i>69.7</i>
5	<i>62.3</i>	<i>76.1</i>	<i>76.1</i>	<i>69.9</i>
6	<i>62.7</i>	<i>77.6</i>	<i>75.4</i>	<i>68.3</i>
7	<i>63.6</i>	<i>78.7</i>	<i>71.6</i>	<i>68.9</i>
8	<i>57.7</i>	<i>-</i>	<i>60.8</i>	<i>61.4</i>
9	<i>-</i>	<i>60</i>	<i>59.4</i>	<i>62.7</i>
10	<i>-</i>	<i>61.4</i>	<i>61.1</i>	<i>61.6</i>
11	<i>-</i>	<i>61.4</i>	<i>58.6</i>	<i>59.4</i>
12	<i>59.2</i>	<i>55.3</i>	<i>65.5</i>	<i>64.1</i>

Notes:

* large lawn mower running on shore.



Sound Study Location Points